CCN #18	083734 – T	raffic Cras	h Report							
REPORT DATE / TIME DISTRICT / PSA EVENT START DATE			E / TIME - EVENT END DATE / TIME INCIDENT STATISTICS							
May 24, 2018	3 16:51	Second Distri	ct / 203	May 24, 2018	16:11 -					
RESPONDING OFF				WEATHER						
	ZIER (#5617) – M	PD								
ASSISTING OFFICE	ER (ASSIST TYPE)									
TELETYPE DATE / TIME TELETYPE # WHO				WHO NOTIFIED TEL	.ETYPE		REPORTING PERS	ON (FIRST, MIDDLE LAST)		
MAJOR CRASH NO	TIFIED	PERSON NOTIFIED		1		DATE / TIME NOTII	FIED			
	/EHICLES /	NON-MO	TORISTS IN	NVOLVED						
REFERENCE #	NAME / DESCRIPTI					# OF PERSONS (IN	VEHICLE)	VEHICLE TAG # OR PERSON DOB		
v-1	HOND HOND	A CIVIC (AND CR	X)			3				
REFERENCE #	NAME / DESCRIPTI	ON				# OF PERSONS (IN	VEHICLE)	VEHICLE TAG # OR PERSON DOB		
v-2	LINC LINCOLN	N-CONTINENTAL	. MKZ			1				
REFERENCE #	NAME / DESCRIPTI					# OF PERSONS (IN	VEHICLE)	VEHICLE TAG # OR PERSON DOB		
v-3	VOLK VOLKSV	VAGEN JETTA				1				
CRASH D	ETAILS									
REPORT TAKEN O	N SCENE	SCHOOL BUS RELA	TED			# OF PHOTOS TAKI	EN			
YES NO		No				53				
# OF VEHICLES IN	VOLVED	# OF INJURED PERS	ONS	# OF FATALITIES						
3		3		0						
DAYS INN - C		'ENUE, 4400 CO	NNECTICUT AVE	NUE NW, WASH	INGTON, DC 200	008 Type: Higl	hway/ Road/ Al	lley/ Street/ Sidewalk Public/		
Private: Pub	lic PSA: 203 Di	strict: Second [District							
TRAFFICWAY LOC			INTERSECTION TYP			POSITION (BEHIND), FRONT, INSIDE, SID	E)		
Trafficway, C			Not an Interse	ction						
LOCATION DESCR	IPTION									
WORK ZONE-RELA	ATED	WORKERS PRESEN	T	LOCATION WITHIN	WORK ZONE					
YES NO		YES NO								
WORK-ZONE TYP	E			LAW ENFORCEMEN	LAW ENFORCEMENT PRESENCE					
POSTED SPEED LI	MIT	TRAFFIC CONDITIO	NS		STREET LIGHTS					
30		Heavy			Street Lights Off					
LIGHTING CONDIT	TIONS				ROADWAY SURFACE CONDITIONS					
Daylight					Dry					
	IRCUMSTANCES: ROAD)			CONTRIBUTING CIRCUMSTANCES: ENVIRONMENTAL					
None,		- 0.00 (DD-D)			None,					
	EVENT (WHERE DAMAG VITH_NON_FIXED				EVENT TYPE DETAILS Motor Vehicle In Transport					
COLLISION IMPAC		,	LOCATION RELATIV	/F TO TRAFFICWAY	Wotor vernicle	z III Transport				
Angle			On Roadway							
WITHIN INTERCHA	ANGE	LOCATION WITHIN								
YES NO										
FULL SEC	QUENCE OI	F EVENTS								
EVENT#	VEH / NM / OBJ RE		EVENT TYPE			EVENT SPECIFICS				
1	HOND HONDA	A CIVIC (AND	COLLISION_W	TH_NON_FIXED)	Motor Vehicle	e In Transport			
	CRX)						· .			
	COLLIDED WITH				COLLISION IMPACT					
		N-CONTINENTAL	1		Angle					
EVENT#	VEH / NM / OBJ REI	FERENCE #	EVENT TYPE	THE NON-TWEE		EVENT SPECIFICS	a la Terrer			
2	LINC COLLISION_WITH_NON_FIXED LINCOLN-CONTINENTAL MKZ			D Motor Vehicle In Transport						

COLLIDED WITH	COLLISION IMPACT
VOLK VOLKSWAGEN JETTA	Angle

MOST HARMFUL EVENTS INSTRUCTIONS: LIST ONLY MOTOR VEHICLES FROM SEQUENCE OF EVENTS AND ITS CORRESPONDING MOST HARMFUL EVENT.

VEHICLE REFERENCE #	EVENT#
v-1	Event #2 – COLLISION_WITH_NON_FIXED: Motor Vehicle In Transport
VEHICLE REFERENCE #	EVENT#
v-2	Event #2 – COLLISION_WITH_NON_FIXED: Motor Vehicle In Transport
VEHICLE REFERENCE #	EVENT#
v-3	Event #1 – COLLISION WITH NON FIXED: Motor Vehicle In Transport

NARRATIVE

The accident occurred in the 4400 blk of Conn. Ave NW D-1 states that as she was driving S/B in the 4400 blk D-2 pulled into her lane which caused her to change lanes quickly and cause her to over correct the vehicle which then cause a roll over. D-2 states that as he was driving in the 4400 blk of Conn. Ave NW D-1 came into his lane striking his vehicle and then lost control and rolled over and came to a rest in the 4400 blk of Conn. Ave NW. D-3 states that as she was parked in the block she didn't see the accident, she felt V-2 strike her vehicle. Due to conflicting stories and possible video from the flagship car wash this investigation is still pending. All passengers in Veh-1 where released from WHC and Sibley. Sgt. Tran took 53 photos of the scene and up loaded them to evidence.com. BWC activated. The witnesses were not on the scene to be interviewed by the reporting officer.

Crash Diagram		
CCN#	EVENT START TIME / DATE – EVENT END DATE / TIME	WEATHER
18083734	May 24, 2018 16:11 -	

LOCATION

DAYS INN - CONNECTICUT AVENUE, 4400 CONNECTICUT AVENUE NW, WASHINGTON, DC 20008 Type: Highway/ Road/ Alley/ Street/ Sidewalk Public/ Private: Public PSA: 203 District: Second District

COORDINATES

38.947586, -77.065631



TC Vehicle Addendu	m – v-1 20	15 HONDA	CIVIC (AND	CRX)				
CCN#	N# VEHICLE REFERENCE #			HIT AND RUN CO		OOUS MATERIALS	HAZMAT SPILLED / RELEASED	
18083734	v-1		YES NO		☐ YES ■ NO		YES NO	
HAZMAT PLACARD	HAZMAT PLACARD	ID / NAME	HAZMAT PLACARD	CLASS#				
YES NO								
VEHICLE INVOLVED			<u> </u>					
MAKE OF VEHICLE	MODEL OF VEHICLE		YEAR MANUFACTUR	RED	VIN / HIN #			
HONDA CIVIC (AND CRX)			2015					
OWNER'S NAME (LAST, FIRST MIDDLE)			OWNER PHONE		TAG OR PLATE # / S	STATE		
OWNER'S ADDRESS								
			T					
OWNER TYPE (PRIVATE/COMMERCIAL/GOVT/UNKNOWN)			MOTOR VEHICLE CL					
Private VEHICLE WAS DRIVEN AWAY / TOWED			Motor Vehicle	<u> </u>			TOWING CONTROL #	
Towed Due To Disabling Dama	220		dtd dtl	TOWING COMPANY			2018tc0087	
TOWER TO LOCATION	age		atu				201010007	
3010 rhode island ave ne								
ACTIONS & DAMAG	 E							
MOTOR VEHICLE ACTION								
Changing Lanes								
VEHICLE-RELATED CONTRIBUTING CIRCU	IMSTANCES		INITIAL CONTACT P	OINT ON VEHICLE		DAMAGED AREAS		
			3-point Clock Diagram				ooint Clock Diagram, 5-point	
EXTENT OF DAMAGE			12		Clock Diagram			
Disabling Damage			11 1				12	
SKID MARKS BEFORE IMPACT (LENGTH IN	N FEET)						1	
20			10	2		10	2	
SKID MARKS AFTER IMPACT (LENGTH IN	FEET)		9	3				
15			8	4		9	3	
DIRECTION OF TRAVEL BEFORE CRASH			7	5		8	4	
Southbound					7 5			
				6			6	
TRAFFICWAY DESCRIPTION				TOTAL LANES IN RO) A D\\/ A V			
Two-way, Divided, Unprotect	ed(nainted > 4f	eet) Median		6	DADWAT			
HORIZONTAL ALIGNMENT OF ROADWAY	cu(pameca > +1	GRADE		0				
Straight		Downhill						
TRAFFIC CONTROL DEVICE TYPE		I.		TRAFFIC CONTROL	DEVICE FUNCTIONAL			
No Controls			YES NO					
DRIVER								
NAME (LAST, FIRST MIDDLE)			DATE OF BIRTH / AGE RANGE		PHONE		DRIVERS LICENSE #	
DL STATE	DL TYPE / CLASS				Į.		1	
DRIVER HAS INSURANCE	INSURANCE COMPANY			POLICY#			EXPIRATION DATE	
DRIVER DICTRACTIONS								
DRIVER DISTRACTIONS Not Distracted,								
DRIVER ACTIONS AT TIME OF CRASH								
Operated Motor Vehicle In Er	ratic. Reckless	Careless Neglio	gent Or Aggressi	ve Manner				
SPEEDING RELATED	, HOURIUSS,		Jone Or Aggressi			NOI#'S		
Exceeded Speed Limit								
DRIVER'S CONDITION AT THE SCENE						I		
Apparently Normal,								
<u> </u>								

RESTRAINTS		HELMET			EJECTION FROM VEHICLE			
Shoulder And Lap Belt Used			No Helmet			Not Ejected		
AIRBAG								
Deployed-combination								
SUSPECTED OF CONSUMING ALCOHOL USING	DRUGS							
PASSENGERS / OCC	UPANTS							
NAME (LAST, FIRST MIDDLE)			DATE OF BIRTH / AG	SE RANGE	PHONE			_
INVOLVEMENT TYPE								
Passenger								
POSITION: ROW		POSITION: SEAT		POSITION: OTHER				
Second		Right						
PERSON'S CONDITION AT THE SCENE								
Apparently Normal			ı			ı		
RESTRAINTS			HELMET			EJECTION FROM VEI	HICLE	
Shoulder And Lap Belt Used			No Helmet			Not Ejected		
AIRBAG Deployed-combination								
SUSPECTED OF								
CONSUMING ALCOHOL USING	DRUGS							
NAME (LAST, FIRST MIDDLE)			DATE OF BIRTH / AG	SE RANGE	PHONE			
INVOLVEMENT TYPE					ı			
Passenger								
POSITION: ROW		POSITION: SEAT		POSITION: OTHER				
Second		Left (usually T						
		Vehicle Or Mo	torcycle Driver					
		Except For Po And Some For						
PERSON'S CONDITION AT THE SCENE		And Some For	eigii veilleles)					
Apparently Normal								
RESTRAINTS			HELMET			EJECTION FROM VEH	HICLE	
Shoulder And Lap Belt Used			No Helmet			Not Ejected		
AIRBAG			ı					
Not Applicable								
SUSPECTED OF								
CONSUMING ALCOHOL USING	DRUGS							
OTHER VEHICLE AT	TRIBUTES							
VEHICLE INSURED	INSURANCE COMPA	NY		POLICY#			EXPIRATION DATE	
YES NO								
SPECIAL FUNCTION			VEHICLE USE AS EM	ERGENCY VEHICLE				
None			Not Applicable	e				
MOTOR CARRIER	CARRIER NAME							
CARRIER ADDRESS								
TYPE OF CARRIER			CARRIER ID TYPE CAR			CARRIER ID#		
GROSS VEHICLE WEIGHT / GROSS COMBI	NATION WEIGHT RATI	NG	CONFIGURATION					
CARGO BODY TYPE								

TC Vehicle Addend	um – v-2 201	L4 LINCOL	N-CONTINE	NTAL MKZ	<u>.</u>		
CCN#	VEHICLE REFERENC	E#	HIT AND RUN		CONTAINS HAZARD	OUS MATERIALS	HAZMAT SPILLED / RELEASED
18083734	v-2		☐ YES ■ NO		YES NO		YES NO
HAZMAT PLACARD YES NO	HAZMAT PLACARD I	D / NAME	HAZMAT PLACARD	CLASS#			
VEHICLE INVOLVE))						
MAKE OF VEHICLE	MODEL OF VEHICLE		YEAR MANUFACTU	RED	VIN / HIN#		
LINCOLN-CONTINENTAL	MKZ		2014	NED	VIIV, TIIIV#		
OWNER'S NAME (LAST, FIRST MIDDLE)	IVIKZ		OWNER PHONE		TAG OR PLATE # / S	TATE	
OWNER S NAME (EAST, THIST MIDDLE)			OWNERTHONE		TAG ONT EATE #7 3		
OWNER'S ADDRESS							
OWNER TYPE (PRIVATE/COMMERCIAL/	GOVT/UNKNOWN)		MOTOR VEHICLE C	LASSIFICATION			
Private			Motor Vehicle	e In Transport			
VEHICLE WAS DRIVEN AWAY / TOWED			DRIVEN AWAY BY /	TOWING COMPANY			TOWING CONTROL#
Towed Due To Disabling Dan	nage		dtd				2018tc0086
TOWED TO LOCATION							
3010 rhode island ave ne							
ACTIONS & DAMAG	SE						
MOTOR VEHICLE ACTION							
Movements Essentially Strai	ight Ahead						
VEHICLE-RELATED CONTRIBUTING CIRC	CUMSTANCES		INITIAL CONTACT F			DAMAGED AREAS	
			11-point Cloc			11-point Clock Diagram, 1-point Clock	
EXTENT OF DAMAGE				12	_		oint Clock Diagram, 10-point
Disabling Damage			11	1		Clock Diagra	m 12
SKID MARKS BEFORE IMPACT (LENGTH	IN FEET)		10	2			
0						11	1
SKID MARKS AFTER IMPACT (LENGTH IN	N FEET)		9	3		10	_ / 2
0			8	4		9	3
DIRECTION OF TRAVEL BEFORE CRASH			7	5			
Southbound						- 8	4
				6		7	5
							6
TRAFFICWAY DESCRIPTION				TOTAL LANES IN RO	DADWAY		
Two-way, Divided, Unprotec	-			6			
HORIZONTAL ALIGNMENT OF ROADWA	ıΥ	GRADE					
Straight		Downhill		I			
TRAFFIC CONTROL DEVICE TYPE					DEVICE FUNCTIONAL		
No Controls				YES NO			
DRIVER			_				
NAME (LAST, FIRST MIDDLE)			DATE OF BIRTH / A	GE RANGE	PHONE		DRIVERS LICENSE #
DL STATE	DL TYPE / CLASS						
DRIVER HAS INSURANCE	INSURANCE COMPANY			POLICY#			EXPIRATION DATE
DRIVER DISTRACTIONS							
Not Distracted,							
DRIVER ACTIONS AT TIME OF CRASH							
No Contributing Action						NO. III	
SPEEDING RELATED No						NOI#'S	

DRIVER'S CONDITION AT THE SCENE							
Apparently Normal,							
RESTRAINTS		HELMET		EJECTION FROM VEI	HICLE		
Shoulder And Lap Belt Used		No Helmet		Not Ejected			
AIRBAG							
Deployed-front							
SUSPECTED OF							
CONSUMING ALCOHOL USING I	DRUGS						
PASSENGERS / OCC	UPANTS						
OTHER VEHICLE AT	TRIBUTES						
VEHICLE INSURED	INSURANCE COMPANY		POLICY#		EXPIRATION DATE		
YES NO							
SPECIAL FUNCTION		VEHICLE USE AS EMERGENCY VEHICLE					
None		Not Applicable					
MOTOR CARRIER	CARRIER NAME						
CARRIER ADDRESS							
TYPE OF CARRIER		CARRIER ID TYPE		CARRIER ID#			
GROSS VEHICLE WEIGHT / GROSS COMBINATION WEIGHT RATING		CONFIGURATION					
CARGO BODY TYPE							

ic venicie Addendu	m – v-3 2U	TS AOFK2A	VAGEN JE I	IA				
CCN#	VEHICLE REFERENCE # HIT AND RUN			CONTAINS HAZAR		OUS MATERIALS	HAZMAT SPILLED / RELEASED	
18083734	v-3		☐ YES ■ NO		YES NO		YES NO	
HAZMAT PLACARD	HAZMAT PLACARD	ID / NAME	HAZMAT PLACARD	CLASS#				
YES NO								
VEHICLE INVOLVED								
MAKE OF VEHICLE	MODEL OF VEHICLE		YEAR MANUFACTUR	RED	VIN / HIN #			
VOLKSWAGEN	JETTA		2012					
OWNER'S NAME (LAST, FIRST MIDDLE)	J=		OWNER PHONE		TAG OR PLATE # / S	TATE		
OWNER'S ADDRESS			ı		J			
OWNER TYPE (PRIVATE/COMMERCIAL/G	OVT/UNKNOWN)		MOTOR VEHICLE CL	ASSIFICATION				
Private			Motor Vehicle	In Transport				
VEHICLE WAS DRIVEN AWAY / TOWED			DRIVEN AWAY BY /	· · · · · · · · · · · · · · · · · · ·			TOWING CONTROL#	
Towed Due To Disabling Dama	age		aaa				n/a	
TOWED TO LOCATION	-							
3328 banneker st ne								
ACTIONS & DAMAG	E							
MOTOR VEHICLE ACTION								
Parked								
VEHICLE-RELATED CONTRIBUTING CIRCU	JMSTANCES		INITIAL CONTACT P	OINT ON VEHICLE		DAMAGED AREAS		
			11-point Clock	k Diagram	3-point Clock		Diagram, 10-point Clock	
EXTENT OF DAMAGE				12		Diagram, 11-point Clock Diagram		
Disabling Damage			11	1			12	
SKID MARKS BEFORE IMPACT (LENGTH IN	N FEET)				11 11		1	
0			10	- 2		10	2	
SKID MARKS AFTER IMPACT (LENGTH IN	FEET)		9	3				
0			8 4			9 3		
DIRECTION OF TRAVEL BEFORE CRASH						8	4	
Southbound			7 5		_	7	5	
				6				
							6	
TRAFFICWAY DESCRIPTION			TOTAL LANES IN ROADWAY					
Two-way, Divided, Unprotect	ed(painted > 4f	eet) Median		6				
HORIZONTAL ALIGNMENT OF ROADWAY		GRADE						
Straight		Downhill						
TRAFFIC CONTROL DEVICE TYPE			TRAFFIC CONTROL DEVICE FUNC					
No Controls			YES NO					
DRIVER								
NAME (LAST, FIRST MIDDLE)			DATE OF BIRTH / AGE RANGE		PHONE		DRIVERS LICENSE #	
DL STATE	DL TYPE / CLASS							
DRIVER HAS INSURANCE	INSURANCE COMPANY			POLICY#			EXPIRATION DATE	
PRINCE PROTECTION								
DRIVER DISTRACTIONS								
Not Distracted								
DRIVER ACTIONS AT TIME OF CRASH								
No Contributing Action,								
SPEEDING RELATED						NOI#'S		
No								
DRIVER'S CONDITION AT THE SCENE								
Apparently Normal,								

RESTRAINTS		HELMET		EJECTION FROM VEHICLE			
Shoulder And Lap Belt Used		No Helmet		Not Ejected			
AIRBAG							
Not Applicable							
SUSPECTED OF							
CONSUMING ALCOHOL USING	DRUGS						
PASSENGERS / OCC	CUPANTS						
OTHER VEHICLE AT	TRIBUTES						
VEHICLE INSURED	INSURANCE COMPANY		POLICY#		EXPIRATION DATE		
YES NO							
SPECIAL FUNCTION		VEHICLE USE AS EMERGENCY VEHICLE					
None		Not Applicable					
MOTOR CARRIER	CARRIER NAME						
CARRIER ADDRESS							
TYPE OF CARRIER		CARRIER ID TYPE		CARRIER ID#			
GROSS VEHICLE WEIGHT / GROSS COMBINATION WEIGHT RATING		CONFIGURATION					
CARGO BODY TYPE							

CCN #18083734 - NARRATIVE

The accident occurred in the 4400 blk of Conn. Ave NW D-1 states that as she was driving S/B in the 4400 blk D-2 pulled into her lane which caused her to change lanes quickly and cause her to over correct the vehicle which then cause a roll over. D-2 states that as he was driving in the 4400 blk of Conn. Ave NW D-1 came into his lane striking his vehicle and then lost control and rolled over and came to a rest in the 4400 blk of Conn. Ave NW. D-3 states that as she was parked in the block she didn't see the accident, she felt V-2 strike her vehicle. Due to conflicting stories and possible video from the flagship car wash this investigation is still pending. All passengers in Veh-1 where released from WHC and Sibley. Sgt. Tran took 53 photos of the scene and up loaded them to evidence.com. BWC activated. The witnesses were not on the scene to be interviewed by the reporting officer.